
MODELS: 1770S1P, 1780S1P, 1790S1P

IMPORTANT - READ CAREFULLY BEFORE INSTALLING FIXTURE. RETAIN THESE INSTRUCTIONS FOR FUTURE REFERENCE.
THIS PRODUCT MUST BE INSTALLED IN ACCORDANCE WITH THE NATIONAL ELECTRICAL CODE AND ALL APPLICABLE LOCAL CODES, BY A PERSON FAMILIAR WITH THE CONSTRUCTION AND OPERATION OF THE PRODUCT, AND THE HAZARDS INVOLVED. PROPER GROUNDING IS REQUIRED FOR SAFETY. CABLE LENGTH IS NOT FIELD AJUSTABLE, CONTACT FACTORY TO SPECIFY CABLE LENGTH.

INSTALLATION ON ONE CIRCUIT TRACK WITH HALO ADAPTOR

FOR USE WITH WESTPORT INTERNATIONAL'S H SERIES OR COOPER LIGHTING'S L641, L642, L643, L650, L651, L652, L653 SERIES. TRACK SYSTEM ONLY (120V)

- A PULL THE ADAPTOR HOUSING DOWN TO INSERT IN THE TRACK FOLLOWING INITIAL POSITION SHOWN BELOW.
- B PUSH THE ADAPTOR INTO TRACK AND ROTATE THE TRACK ADAPTOR A QUARTER TURN IN THE PROPER DIRECTION IN ORDER TO ALLOW ELECTRICAL BOUNDING. RELEASE THE HOUSING AND MAKE SURE THE ADAPTOR IS LOCKED IN PLACE, FOLLOWING FINAL POSITION SHOWN BELOW.




NS-440S1P


LAST UPDATE: DECEMBER 05, 2017

MD - R

REMOVING PENDANT FROM TRACK

- A PULL DOWN THE TRACK ADAPTOR HOUSING TO UNLOCK IT FROM THE TRACK SLOT.
- B HOLDING THE TRACK ADAPTOR HOUSING DOWN, ROTATE A QUARTER TURN IN ANY DIRECTION AND PULL DOWN THE ADAPTOR TO REMOVE IT FROM THE TRACK.






REPLACING OPTIC

- A UNSCREW THE OPTIC HOLDER TO ACCESS THE REFLECTOR.
- B REPLACE THE REFLECTOR AND RE-INSTALL THE OPTIC HOLDER BACK IN PLACE.

A + B



INS-440S1P

LAST UPDATE: DECEMBER 05, 2017


MD - RO

MODELS: 1770S1P, 1780S1P, 1790S1P

- A UNSCREW THE OPTIC HOLDER.
- B PLACE ACCESSORY BETWEEN THE OPTIC HOLDER AND THE ACCESSORY HOLDER.
- C RE-INSTALL THE OPTIC HOLDER BACK IN PLACE.

A + B + C

ACCESSORIES



INS-440S1P

LAST UPDATE: DECEMBER 05, 2017

MD - R